

Oil Field Environmental Incident Summary

Incident: 20140811150503 **Date/Time of Notice:** 08/11/2014 15:05

Responsible Party: KODIAK OIL & GAS (USA) INC.

Well Operator: KODIAK OIL & GAS (USA) INC.

Well Name: FLATLAND 16-9 SWD

Field Name: BANKS

Well File #: 90151

Date Incident: 8/6/2014 **Time Incident:** 14:00

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 97

Sec: 9

Qtr:

Location Description:

Submitted By: Britiny Fabry

Received By:

Contact Person: Mark Bonnie
1625 BROADWAY STE 250
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	6	Barrels	6	Barrels	6	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 7/17/2015

Clean Up Concluded: 8/11/2014

Risk Evaluation:

Contaminated Facility Soil, confined to facility

Areal Extent:

Potential Environmental Impacts:

Contaminated Facility Soil

Action Taken or Planned:

Standing water was removed with a vac truck. Will allow the soil to dry and will remove contaminated soil and replace it with new soil. Will discuss with operator that such items as open valves must be checked before leaving location.

Wastes Disposal Location: Water was returned to the SWD facility. Soil will be hauled to approved disposal site.

Agencies Involved:**Updates**

Date: 8/13/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.